

92 Washer solvent level warning is on

92 19 23 2038151/10 November 12, 2019. Supersedes Technical Service Bulletin Group 92 number 19-17 dated February 7, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2012 - 2021	All	Not Applicable

Condition

REVISION HISTORY			
Revision	Date	Purpose	
10	-	Revised header (Added MY 2021) Revised <i>Warranty</i> (Added Q3 and Audi e-tron quattro) Revised <i>Service</i> (Added alternative cleaning solution and added alternative suggested washer solvents)	
9	02/07/2019	Revised Warranty (Updated Labor Operations and added A7)	
8	01/23/2019	Revised header (Added new models and model years) Revised Warranty (Corrected Q5 SRTs and added models)	

The washer solvent level warning is on in the driver information system (DIS), but the washer solvent level is correct. There is no functional restriction in the windshield washer system.

Technical Background

The sensitivity of the washer solvent level sensor (G33) can be affected by the type, concentration, and the presence of additives in the washer solvent currently in the tank. The operation of the level sensor relies on the composition of the solvent to provide an accurate message on the solvent level. Incorrect concentration and the presence of additives can contaminate the sensor and reduce its sensitivity.

Production Solution

Not applicable.



Service

If the washer solvent reservoir is full and the low solvent warning is on, proceed as follows:

 Empty the reservoir and for all vehicles <u>except</u> A3 Sedan and A3 Cabriolet, remove the level sensor. Clean the sensor probes using all-purpose cleaner **D 009 401 04** (Figure 1) or, as an alternative, isopropyl alcohol. Reinstall the level sensor.



Figure 1. D 009 401 04 all-purpose cleaner.



 For Audi A3 Sedan and A3 Cabriolet where the washer solvent level sensor is not removable the sensor probes can be cleaned by removing the reservoir, removing the filler neck from the reservoir and gaining access to the sensor probes (Figure 2).



Figure 2. Windshield washer level sensor probes as viewed through the tank opening.



3. Saturate the tip of a cleaning brush with a rigid stem and long enough to reach the probes (approximately 10") with all-purpose cleaner **D 009 401 04** or isopropyl alcohol. A humming bird feeder cleaning brush is shown in the illustration but any suitable cleaning brush with a tip constructed of the appropriate material will function well for this purpose (Figure 3).



Figure 3. Applying all-purpose cleaner D 009 401 04 to the tip of a humming bird feeder cleaning brush. The cleaning brush can alternatively be saturated with isopropyl alcohol.



4. Thoroughly clean the sensor probes (Figure 4).



Figure 4. Cleaning the sensor probes.

5. Refill the reservoir with the correct type and concentration of solvent. Windshield washer fluids found in the Audi Top Service Supplies and Touch Up Paint eStore with a 35% premix are suitable for temperatures down to -30 °C (-22° F) and contain no rain repellents. For freeze protection below this temperature range Windshield Washer Fluid Concentrate ZAW 096 311 B can be used and mixed according to the table below (Figure 5). This solvent can be adjusted for freeze protection to -32° C (-25° F), prevents washer jet contamination particularly on the "fan" type of washer jet, and is highly effective in removing residues and insects from the windshield.



Figure 5. ZAW 096 311 B windshield washer fluid concentrate.



Note:

Dealers in states such as California which have a restriction on windshield washer solvent VOC content can use Audi Windshield Washer Fluid – 35% pre-mix – (55 gallon) available from the Audi Top Service Supplies & Touch-Up Paint eStore as an alternative. This solvent contains no water repellents and has freeze protection to -22° F.

6. The concentration and freeze point can be checked using the T10007A refractometer (Figure 6).




Figure 6. T10007A refractometer.

7. Put a drop of washer fluid with the pipette on the glass of the refractometer. When viewing the refractometer, a light-dark border can be clearly recognized. Using the scale to the right (Figure 7), adjust the concentration of the solvent to accommodate the current weather conditions.




Figure 7. Scale in the view of the T10007A refractometer.

8. Concentration guidelines:



Freeze protection	Windshield Washer Fluid Concentrate ZAW 096 311	Water
-16 °C (3° F)	1 part	3 parts
-30 °C (- 22° F)	1 part	2 parts
-32 °C (- 25° F)	1 part	1.5 parts



It is not necessary to replace the windshield washer solvent level sensor when the cause of failure is contaminated sensor probes or incorrect washer solvent solution. Warranty claims for replacement of washer solvent level sensors that are found to not be faulty will not be reimbursed.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If vehicle is outside any warranty, this Technical Service Bulletin is informational 		
Service Number:	9258		
Damage Code:	0040		
Labor Operations: Q7 (up to and including MY 2015):			
	Lower Windshield washer reservoir remove + reinstall	9260 1900	See SRT
	Fluid level sensor remove + reinstall	9258 1950	See SRT
	Clean fluid level sensor and adjust solvent concentration	9258 9999	10 TU
Q7 (From MY 2016 on):			
	Cover (plenum) remove + reinstall	8522 1900	See SRT
	Fluid level sensor remove + reinstall	9258 1950	See SRT



Clean fluid level sensor and adjust solvent concentration	9258 9999	10 TU
Q3 (From MY 2015 on):		
Front wheel housing liner remove + reinstall	6616 1900	See SRT
Fluid level sensor remove + reinstall	9258 1950	See SRT
Clean fluid level sensor and adjust solvent concentration	9258 9999	10 TU
S3:		
Noise dampening pan remove + reinstall	1082 1900	See SRT
Fluid level sensor remove + reinstall	9258 1950	See SRT
Clean fluid level sensor and adjust solvent concentration	9258 9999	10 TU
A3 Sedan, A3 e-tron, and A3 Cabriolet:		
Front wheel housing liner remove + reinstall	6616 1900	See SRT
Windshield washer reservoir remove + reinstall	9260 1950	See SRT
Clean fluid level sensor and adjust solvent concentration	9258 9999	10 TU
TT:		
Front wheel housing liner remove + reinstall	6616 1900	See SRT
Windshield washer reservoir remove and reinstall	9260 1950	See SRT (2012 – 2015)
		See SRT (2016 – 2019)
Fluid level sensor remove + reinstall, clean fluid level sensor and adjust solvent concentration	9258 9999	20 TU
R8 (up to and including MY 2015):		
Plenum cover remove + reinstall	8522 1900	See SRT
Fluid level sensor remove + reinstall	9258 1950	See SRT



9258 9999	10 TU
8522 1900	See SRT
9258 1950	See SRT
9258 9999	10 TU
et (up to and includ (Model 8R, up to an	ling MY 2017),
9258 1900	See SRT
9258 9999	10 TU
` '	
6616 1900	See SRT
9258 1950	See SRT
9258 9999	10 TU
6616 1900	See SRT
9258 1950	See SRT
9258 9999	10 TU
66 44 19 00	See SRT
9258 1950	See SRT
	8522 1900 9258 1950 9258 9999 Ip to and including et (up to and includ (Model 8R, up to and Y 2019 on): 9258 1900 9258 9999 Illroad (MY 2017 on) odel FY, MY 2018 on 6616 1900 9258 1950 9258 9999 6616 1900 9258 1950 9258 9999




	Clean fluid level sensor and adjust solvent concentration	9258 9999	10 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2038151/10		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
T10007A	Refractometer	01
ZAW 096 311 B (item number 128429)	Windshield Washer Fluid Concentrate	01
(Available from the Audi Top Service Supplies & Touch- Up Paint eStore)		









Additional Information

All parts and service references provided in this TSB (2038151) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.